

RE: Lear Corporation  
FCC ID: KOBFR04D186

This is in response to the comments made on the above application.

1) The 731 form shows that this application is for a receiver. However, from the operational and internal photographs this is not easily determined. Please provide a photograph that shows/labels the portion of the device that is the RX and also the antenna for the RX.

Additional internal photographs have been uploaded demonstrating the RX circuitry and the antenna.

2) The block diagram should show the frequencies of the oscillator within the device (CFR 2.1033(a)(5)). Please provide an updated version that includes this information.

A revised Block Diagram has been uploaded.

3) Please provide a higher resolution schematic. The values/designators were not distinguishable.

A higher resolution schematic has been requested from the manufacturer and will be uploaded as soon as possible.

4) The label appears to show the FCC ID as KOBFR04D186, while the label appears as KOBFR04D186. Please confirm which FCC ID Number is correct using a '0' or 'O'.

This is a simple typo, the FCC ID is KOBFR04D186 and a revised ID label has been uploaded.

5) Please provide a photograph that shows the placement of the label on the device.

See revised ID Label & Location Exhibit.