



5200 Auto Club Dr.
Dearborn, MI 48126
(313) 593-9000

Date: April 16, 2002

Re: Certification for Lear Corporation, Receiver Model RLC-C+.

Description of Changes

For the following module:

| Model | FCC ID | Canada ID |
|--------------|---------------|------------------|
| RLC-C+ | KOBLEAR1CR | 1983 102 282A |

The following changes were made:

Change capacitors C62 and C65 from 0.22 uF to 0.1 uF.
Added capacitors C60 and C70, 0.1 uF.