



5200 Auto Club Dr.  
Dearborn, MI 48126  
(313) 593-9000

Date: April 16, 2002

**Re: Certification for Lear Corporation, Receiver Model RLC-X.**

### **Description of Changes**

For the following modules:

<b>Model</b>	<b>FCC ID</b>	<b>Canada ID</b>
RLC-X	KOBLEAR1XR	1983 102 283A

The following changes were made:

- Change capacitors C62 and C65 from 0.22 uF to 0.1 uF.
- Added capacitors C60 and C70, 0.1 uF.
- Added capacitor C69, 0.22 uF.
- Rerouted traces and added more ground plane.