


Test setup photographs







Rogers Labs, Inc.
 4405 West 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Laird Technologies
 Model: LT1110-10
 Test #: 100714
 Test to: CFR47 Parts 2 and 15.247, RSS-210
 File: TSup LT1110

FCC ID#: KQL-111010
 IC: 2268C- 111010
 SN: ENG PRM210/211
 Date: August 16, 2010
 Page 2 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Laird Technologies
Model: LT1110-10
Test #: 100714
Test to: CFR47 Parts 2 and 15.247, RSS-210
File: TSup LT1110

FCC ID#: KQL-111010
IC: 2268C- 111010
SN: ENG PRM210/211
Date: August 16, 2010
Page 3 of 5





Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Laird Technologies
Model: LT1110-10
Test #: 100714
Test to: CFR47 Parts 2 and 15.247, RSS-210
File: TSup LT1110

FCC ID#: KQL-111010
IC: 2268C- 111010
SN: ENG PRM210/211
Date: August 16, 2010
Page 5 of 5