




## Internal photographs of the Equipment Under Test



Loop antenna inside the plastic housing of the ignition lock  
Antenna area:  $0.00071 \text{ m}^2$







RF Part of the Immobilizer

