

Mode : Charging

Report No.: 98075261

Tested By: Hong, Report No.: 98075261

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Praamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QF

Transducer No. Start

Stop

Name

Meas Time: 1 s


3 9k

30M

EI078

Subranges: 16

Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Mode: charging

Report No.: 98075261

Tested By: Hong, Report No.: 98075261

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
3.59500	31.7	48.0

* limit exceeded

Ctrl. No.: N/A

Report No.: 98075261

Mode: STAND BY

Tested By: Hong, Report No.: 98075261

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----


Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QF

Transducer No.	Start	Stop	Name
3	9k	30M	EI076

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

dBuV



Ctrl. No.: N/A

Report No.: 98075261

Mode = STAND BY

Tested By: Hong, Report No.: 98075261

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamplifier	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

Report No.: 98075261

Mode: TX

Tested By: Hong, Report No.: 98075261


Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpAge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF	
								60dB	

Final Measurement: X QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl. No.: N/A

FCC ID: KT5HP228

Report No.: 98075261

Mode: TX

Tested By: Hong, Report No.: 98075261

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A