



Washington Laboratories, Ltd.

7560 LINDBERGH DRIVE
GAITHERSBURG, MD 20879
(301) 417 - 0220 FAX # (301) 417 - 9069

June 23, 2004

Mr. Dennis Ward
American Telecommunications Certification Body Inc.
6731 Whittier Ave
McLean, VA 22101

RE: Comments of May 16, 2004
APPLICATION: KTB-HUB97 Broadcast Sports

Dear Mr. Ward:

Below are the comments that you have provided regarding the application for certification referenced above. Our responses to those comments are in ***bold italic***. Many responses refer you to additional exhibit(s) which has been uploaded to the application folder at the ATCB website.

Thank you for your attention. Please feel free to contact us for any additional information that you may require.

Regards,

Gregory M. Snyder
Chief EMC Engineer, Wireless/Telco Services Manager

Brian J. Dettling
Documentation Specialist

WLL Project: 7960

1) Please provide the factory tune up procedure.

R. The Tune-up Procedure has been obtained. Please see exhibit "HUB97 Tune up Procedure.pdf".

2) Please note that the emissions mask plots do not provide the frequency graticules. This makes it very difficult to determine if the mask is properly overlaid. Please provide the vertical graticules for frequency on the plot. Alternately, please clearly and accurately identify the frequencies associated with each change in mask level.

R. This has been addressed. Please see exhibit "HUB97 Test Report Rev 1.pdf".

3) Please note that page 30 of the report refers to 74.637(a)(3) for radiated spurious emissions. Please note that 74.637(a)(3) is for 'vestigial sideband AM video'. It appears that the actual paragraph reference should be 74.637(a)(1)(iii). Please verify and correct as needed.

R. Please see exhibit "HUB97 Test Report Rev 1.pdf".