


APPENDIX B-Page 1 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303


## **B.1** Radiated Measurement at Chamber

Frequency Below to 1GHz

Lie



Side



File Number: C1M1807160

Report Number: EM-F180328


This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan


APPENDIX B-Page 2 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

Stand



Frequency Above to 1GHz

Lie




File Number: C1M1807160 This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.


Report Number: EM-F180328



APPENDIX B-Page 3 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303



Stand



File Number: C1M1807160 This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Report Number: EM-F180328



APPENDIX B-Page 4 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

## **B.2 RF Conducted Measurement**



File Number: C1M1807160

Report Number: EM-F180328

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.