

INTERTEK TESTING SERVICES

Report No.: HK09050175-1




RBW 1 MHz Marker 1 [T1]
VBW 3 MHz -22.65 dBm
SWT 20 s 680.000000 ms

Ref -10 dBm

Att 20 dB

1 PK
VIEW



Center 433.902 MHz

2 s/

Date: 9.MAY.2009 11:40:33




RBW 1 MHz Marker 1 [T1]
VBW 3 MHz -23.26 dBm
SWT 800 ms 694.400000 ms

Ref -10 dBm

Att 20 dB

1 PK
VIEW



★
A
SGL

Center 433.902 MHz

80 ms/

Date: 11.MAY.2009 09:36:13