




Radiated Test Placement: (Photographs)



Report No.: C0915894, 10/100 PCI Ethernet Adapter, FCC Class B

Test date: 10/19/98, Training Research Co., Ltd., TEL: 886-2-26461146, Fax: 886-2-26461778

Conducted Test Placement: (Photographs)



Report No.: C0915894, 10/100 PCI Ethernet Adapter, FCC Class B

Test date: 10/19/98, Training Research Co., Ltd., TEL: 886-2-26461146, Fax: 886-2-26461778