
SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC TEST REPORT

REPORT NO.: F841510

6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION



FRONT VIEW



REAR VIEW

APPLICANT : CIS TECHNOLOGY INC.

EQUIPMENT: WS-NWG4

FCC ID : L40NWG4


ISSUED DATE : APR. 16, 1998

PAGE NUMBER: 21 OF23

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC TEST REPORT

REPORT NO.: F841510



SIDE VIEW

APPLICANT : CIS TECHNOLOGY INC.

EQUIPMENT: WS-NWG4

F C C I D : L40NWG4 ISSUED DATE : APR. 16, 1998 PAGE NUMBER : 16 OF23 SPORTON International Inc.

TEL: 886-2-2696-2468


FCC TEST REPORT

REPORT NO.: F841510

5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION



FRONT VIEW



REAR VIEW

APPLICANT : CIS TECHNOLOGY INC.

EQUIPMENT : WS-NWG4

F C C I D : L4ONWG4 ISSUED DATE : APR. 16, 1998 PAGE NUMBER : 15 OF23