

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F831902


5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

TP MODE

FRONT VIEW



REAR VIEW



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F831902

6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

TP MODE

FRONT VIEW



REAR VIEW



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F831902


5.5.1 PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

BNC MODE

FRONT VIEW



REAR VIEW



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F831902

SIDE VIEW



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F831902

SIDE VIEW



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


FCC TEST REPORT

REPORT NO. : F831902

6.5.1 PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

BNC MODE

FRONT VIEW



REAR VIEW

