2.983 Tune up Procedure:

All frequency adjustments are set at the factory and there are no frequency field adjustments for this product. Under Digital Mode, frequency is locked to the base station and controlled by VCTCXO adjustments to offset any possible errors.

Arlie Payne

Senior Regulatory Engineer QUALCOMM Incorporated