

RTS

RIM Testing Services (RTS),
A Division of Research In Motion

Research In Motion Limited
295 Phillip Street
Waterloo, Ontario
Canada N2L 3W8
+1 519 888 7465, fax +1 519 888 6906
E-mail: info@rim.com

August 11, 2006

Stan Lyles
Federal Communications Commission,
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21045

Subject: Response to the FCC Correspondence Reference # 31374 for additional information on RIM BlackBerry Handheld FCC ID: L6ARAV20CW, 731 Confirmation # EA459850.

Dear Stan,

The following addresses the comment on your **Correspondence Reference # 31374**, dated August 10, 2006.

RF emission and T-coil rating must use the same version of the C63.19 standard. Please provide an updated RF emission report to support the T-coil test.

Please refer to the revised test reports "HAC Test Report rev 02.pdf" and "HAC T-Coil Test Report rev 03.pdf" as per your request.

Please do not hesitate to contact the undersigned should you have any questions.

Yours truly,



Masud S. Attayi, P.Eng.
Senior Compliance Engineer,
RTS (RIM Testing Services)
A Division of Research In Motion Limited
Tel: +1 519 888-7465 x2442
Fax: +1 519 888-6906
Email: mattayi@rim.com