

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® smartphone model RBJ41GW		Page 1(6)
Author Data Daoud Attayi	Dates of Test June 01-05, 2007	Report No RTS-0510-0706-05	FCC ID L6ARBJ40GW

Annex C: Test set up photos

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® smartphone model RBJ41GW		Page 2(6)
	Author Data Daoud Attayi	Dates of Test June 01-05, 2007	Report No RTS-0510-0706-05

Acoustic output center

Axial T-Coil Center



Voice microphone

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® smartphone model RBJ41GW		Page 3(6)
	Author Data Daoud Attayi	Dates of Test June 01-05, 2007	Report No RTS-0510-0706-05

Figure 1 - BlackBerry® smartphone

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® smartphone model RBJ41GW		Page 4(6)
	Author Data Daoud Attayi	Dates of Test June 01-05, 2007	Report No RTS-0510-0706-05




Figure 2 – Dipole validation setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® smartphone model RBJ41GW		Page 5(6)
	Author Data Daoud Attayi	Dates of Test June 01-05, 2007	Report No RTS-0510-0706-05




Figure 3 – PMF measurement setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® smartphone model RBJ41GW		Page 6(6)
	Author Data Daoud Attayi	Dates of Test June 01-05, 2007	Report No RTS-0510-0706-05





Figure 4 – HAC RF emissions test setup