

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for Blackberry® Smartphone Model RBK41CG		Page 1(5)
	Author Data Daoud Attayi	Dates of Test March 08-09, 2007	Report No RTS-0491-0811-15

Annex E: Test Setup Photos

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for Blackberry® Smartphone Model RBK41CG		Page 2(5)
	Author Data Daoud Attayi	Dates of Test March 08-09, 2007	Report No RTS-0491-0811-15
		FCC ID L6ARBK40CG	



Figure E1: Blackberry® Smartphone

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for Blackberry® Smartphone Model RBK41CG		Page 3(5)
	Author Data Daoud Attayi	Dates of Test March 08-09, 2007	Report No RTS-0491-0811-15



Figure E2: Probe calibration and reference signal measurement setup

RTS RIM Testing Services	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone Model RBK41CG		Page
	Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	March 08-09, 2007	RTS-0491-0811-15	L6ARBK40CG	4(5)




Figure E3: Ambient noise measurement setup

RTS RIM Testing Services	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for Blackberry® Smartphone Model RBK41CG		Page
	Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	March 08-09, 2007	RTS-0491-0811-15	L6ARBK40CG	5(5)




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup