RTS RIM Testing Services	Annex C to Hearing Aid C Report for BlackBerry® Sn			Page 1(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	21-22 Aug, 2007	RTS-0736-0708-15 Rev1	L6ARBS20CW	1

Annex C: Test set up photos

RTS RIM Testing Services	Annex C to Hearing Aid Concept Report for BlackBerry® Sm			Page 2(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	21-22 Aug, 2007	RTS-0736-0708-15 Rev1	L6ARBS20CW	7



Figure 1. BlackBerry Smartphone

RTS RIM Testing Services	Annex C to Hearing Aid Co Report for BlackBerry® Sm			Page 3(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	21-22 Aug, 2007	RTS-0736-0708-15 Rev1	L6ARBS20CW	7




Figure 2 – Dipole validation setup

RTS RIM Testing Services	Annex C to Hearing Aid Co Report for BlackBerry® Sm			Page 4(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	21-22 Aug, 2007	RTS-0736-0708-15 Rev1	L6ARBS20CW	7



Figure 3 – PMF measurement setup

RTS RIM Testing Services	Annex C to Hearing Aid Co Report for BlackBerry® Sm			Page 5(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	21-22 Aug, 2007	RTS-0736-0708-15 Rev1	L6ARBS20CW	I




Figure 4 – HAC RF emissions test setup