

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBJ41GW		Page 1(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03

Annex E: Test Setup Photos

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBJ41GW		Page 2(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03



Figure E1: BlackBerry® Smartphone

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBJ41GW		Page 3(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03



Figure E2: Probe calibration and reference signal measurement setup

RTS RIM Testing Services	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBJ41GW		Page
	Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	08-24 Dec, 07 and 07 Jan, 08	RTS-0943-0801-03	L6ARBU20CW	4(5)




Figure E3: Ambient noise measurement setup

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBJ41GW		Page 5(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup