

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBY41GW		Page 1(5)
Author Data Daoud Attayi	Dates of Test June 22-25, 2008	Report No RTS-1114-0806-10	FCC ID L6ARBY40GW

Annex C: Test set up photos

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBY41GW		Page 2(5)
	Author Data Daoud Attayi	Dates of Test June 22-25, 2008	Report No RTS-1114-0806-10

Acoustic/T-coil output center



Voice microphone

Figure 1 - BlackBerry® Smartphone

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBY41GW		Page 3(5)
	Author Data Daoud Attayi	Dates of Test June 22-25, 2008	Report No RTS-1114-0806-10





Figure 2 – RF Ambient Noise measurement setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBY41GW		Page 4(5)
	Author Data Daoud Attayi	Dates of Test June 22-25, 2008	Report No RTS-1114-0806-10





Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

RTS RIM Testing Services	Document	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBY41GW		Page 5(5)
	Author Data Daoud Attayi	Dates of Test June 22-25, 2008	Report No RTS-1114-0806-10	FCC ID L6ARBY40GW




Figure 4 – HAC RF emissions test setup