

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBY41GW		Page 1(5)
	Author Data Daoud Attayi	Dates of Test June 17-19, 2008	Report No RTS-1114-0806-11

Annex E: Test Setup Photos

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBY41GW		Page 2(5)
	Author Data Daoud Attayi	Dates of Test June 17-19, 2008	Report No RTS-1114-0806-11

Axial Field/Acoustic/T-coil output center

Radial T

Radial L



Voice microphone

Figure 1 - BlackBerry® Smartphone

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBY41GW		Page 3(5)
	Author Data Daoud Attayi	Dates of Test June 17-19, 2008	Report No RTS-1114-0806-11




Figure E2: Probe calibration and reference signal measurement setup

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBY41GW	Page 4(5)	
	Author Data Daoud Attayi	Dates of Test June 17-19, 2008	Report No RTS-1114-0806-11





Figure E3: Ambient noise and system validation measurement setup

RTS RIM Testing Services	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RBY41GW		Page
	Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	June 17-19, 2008	RTS-1114-0806-11	L6ARBY40GW	5(5)




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup