RTS RIM Testing Services	Annex C to Hearing Aid C Report for the BlackBerry			Page 1(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	June 25, Oct 23-24, 2008	RTS-1271-0810-32	L6ARCD20IN	

Annex C: Test set up photos

RTS RIM Testing Services	Annex C to Hearing Aid (Report for the BlackBerry			Page 2(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	June 25, Oct 23-24, 2008	RTS-1271-0810-32	L6ARCD20IN	

Audio Output

Headset Jack



Figure 1. BlackBerry Smartphone

Voice Microphone


RTS RIM Testing Services	Annex C to Hearing Aid (Report for the BlackBerr			Page 3(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	June 25, Oct 23-24, 2008	RTS-1271-0810-32	L6ARCD20IN	





Figure 2 – RF Ambient Noise measurement setup

RTS RIM Testing Services	Annex C to Hearing Aid (Report for the BlackBerr			Page 4(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	June 25, Oct 23-24, 2008	RTS-1271-0810-32	L6ARCD20IN	







Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

RTS RIM Testing Services	Annex C to Hearing Aid C Report for the BlackBerry			Page 5(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	June 25, Oct 23-24, 2008	RTS-1271-0810-32	L6ARCD20IN	






Figure 4 – HAC RF emissions test setup