RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Coil Test Report for BlackBerry® Sma	6		Page 1(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Dec 03-04, 2008	RTS-1364-0812-11	L6ARCE20C	W

Annex E: Test Setup Photos

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T- Coil Test Report for BlackBerry® Smartphone model RCE21CW			Page 2(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Dec 03-04, 2008	RTS-1364-0812-11	L6ARCE200	CW



Voice microphone

Figure 1 - BlackBerry® Smartphone

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T- Coil Test Report for BlackBerry® Smartphone model RCE21CW			Page 3(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Dec 03-04, 2008	RTS-1364-0812-11	L6ARCE20C	CW



Figure E2: Probe calibration and reference signal measurement setup

Copyright 2005-2008, RIM Testing Services (RTS), a division of Research In Motion Limited This report shall <u>NOT</u> be reproduced except in full without the written consent of RTS

RTS RIM Testing Services	e .	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T- Coil Test Report for BlackBerry® Smartphone model RCE21CW		
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Dec 03-04, 2008	RTS-1364-0812-11	L6ARCE20C	W




Figure E3: Ambient noise and system validation measurement setup

Copyright 2005-2008, RIM Testing Services (RTS), a division of Research In Motion Limited This report shall <u>NOT</u> be reproduced except in full without the written consent of RTS

RTS RIM Testing Services	Document Annex E to Hearing Aid Compatibil Coil Test Report for BlackBerry® St	•	, ,	Page 5(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Dec 03-04, 2008	RTS-1364-0812-11	L6ARCE200	CW




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup