RTS RIM Testing Services	Annex C to Hearing Aid Consequence Report for the BlackBerry			Page 1(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Nov 18, Dec 09-10, 2008	RTS-1364-0812-12	L6ARCE20CW	

Annex C: Test set up photos

RTS RIM Testing Services	Annex C to Hearing Aid ( Report for the BlackBerr			Page 2(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Nov 18, Dec 09-10, 2008	RTS-1364-0812-12	L6ARCE20CW	

## Acoustic/T-coil output center



Figure 1 - BlackBerry® Smartphone

RTS RIM Testing Services	Annex C to Hearing Aid C Report for the BlackBerry			Page 3(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Nov 18, Dec 09-10, 2008	RTS-1364-0812-12	L6ARCE20CW	







Figure 2 – RF Ambient Noise measurement setup

RTS RIM Testing Services	Annex C to Hearing Aid C Report for the BlackBerry			Page 4(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Nov 18, Dec 09-10, 2008	RTS-1364-0812-12	L6ARCE20CW	






Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

RTS RIM Testing Services	Annex C to Hearing Aid Report for the BlackBerr			Page 5(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Nov 18, Dec 09-10, 2008	RTS-1364-0812-12	L6ARCE20CW	






Figure 4 – HAC RF emissions test setup