


| | | | |
|---|---|-------------------------|-------------------|
|  | Document | | Page |
| | Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCY71UW | | 1(4) |
| Author Data | Dates of Test | Report No | FCC ID |
| Daoud Attayi | Mar. 08-10, 2010 | RTS-2337-1003-23 | L6ARCY70UW |

Annex E: Test set up photos


| | | | |
|---|---|--|--------------------------------------|
|  | Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCY71UW | | Page 2(4) |
| | Author Data Daoud Attayi | Dates of Test Mar. 08-10, 2010 | Report No RTS-2337-1003-23 |



Figure E1. BlackBerry Smartphone





Figure E2: Ambient noise and system validation measurement setup





Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup