Testing Services™	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW			Page 1(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Jan. 12-13, 2011	RTS-3640-1102-01	L6ARDM70UW	

Annex C: Test set up photos

Testing Services™	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW			Page 2(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Jan. 12-13, 2011	RTS-3640-1102-01	L6ARDM70UW	




Figure 1. BlackBerry Smartphone

Testing Services™	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW			Page 3(5)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Jan. 12-13, 2011	RTS-3640-1102-01	L6ARDM70UW	



Figure 2 – Dipole Validation & Probe Modulation Factor measurement setup

Testing Services™ Document

Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW

Page 4(5)

Author Data

Daoud Attayi


Dates of Test

Jan. 12-13, 2011

Report No RTS-3640-1102-01

FCC ID

L6ARDM70UW






Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

Testing Services™ Document

Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW

Page

5(5)

Daoud Attayi

Dates of Test


Jan. 12-13, 2011

RTS-3640-1102-01

Report No

L6ARDM70UW

FCC ID






Figure 4 – HAC RF emissions test setup