




|   |   |                                      |  |
|---|---|--------------------------------------|--|
|  | Document<br><b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/RDN71UW</b> |                                      | Page<br><b>1(4)</b>                              |
| Author Data<br><b>Daoud Attayi</b>  | Dates of Test<br><b>Mar. 09-10, 2011</b>  | Report No<br><b>RTS-3640-1103-10</b> | FCC ID<br><b>L6ARDM70UW</b><br><b>L6ARDN70UW</b> |



## Annex E: Test set up photos

|   |   |  |                                      |
|---|---|--|--------------------------------------|
|  | Document<br><b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/RDN71UW</b> |  | Page<br><b>2(4)</b>                  |
|   | Author Data<br><b>Daoud Attayi</b>  | Dates of Test<br><b>Mar. 09-10, 2011</b> | Report No<br><b>RTS-3640-1103-10</b> |






**Figure E1. BlackBerry Smartphone**

|   |   |  |                                      |
|---|---|--|--------------------------------------|
|  | Document<br><b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/RDN71UW</b> |  | Page<br><b>3(4)</b>                  |
|   | Author Data<br><b>Daoud Attayi</b>  | Dates of Test<br><b>Mar. 09-10, 2011</b> | Report No<br><b>RTS-3640-1103-10</b> |



**Figure E2: Ambient noise and system validation measurement setup**

|   |   |  |                                      |
|---|---|--|--------------------------------------|
|  | Document<br><b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/RDN71UW</b> |  | Page<br><b>4(4)</b>                  |
|   | Author Data<br><b>Daoud Attayi</b>  | Dates of Test<br><b>Mar. 09-10, 2011</b> | Report No<br><b>RTS-3640-1103-10</b> |



**Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup**