

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDY71UW			Page 1(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51B RTS-2580-1106-44	FCC ID L6ARDU70CW L6ARDY70UW	

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDY71UW		Page 2(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51B RTS-2580-1106-44	FCC ID L6ARDU70CW L6ARDY70UW



Figure E1. BlackBerry Smartphone

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDY71UW		Page 3(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51B RTS-2580-1106-44	FCC ID L6ARDU70CW L6ARDY70UW





Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDY71UW			Page 4(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51B RTS-2580-1106-44	FCC ID L6ARDU70CW L6ARDY70UW	





Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup