

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/REN71UW</b>		Page <b>1(5)</b>
Author Data <b>Andrew Becker</b>	Dates of Test <b>Mar. 09-10, May 27, July 12, 2011</b>	Report No <b>RTS-3640-1103-10B</b>	FCC ID <b>L6ARDM70UW L6AREN70UW</b>



## Annex E: Test set up photos

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/REN71UW</b>		Page <b>2(5)</b>
	Author Data <b>Andrew Becker</b>	Dates of Test <b>Mar. 09-10, May 27, July 12, 2011</b>	Report No <b>RTS-3640-1103-10B</b>






**Figure E1. BlackBerry Smartphone**

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/REN71UW</b>		Page <b>3(5)</b>
	Author Data <b>Andrew Becker</b>	Dates of Test <b>Mar. 09-10, May 27, July 12, 2011</b>	Report No <b>RTS-3640-1103-10B</b>




**Figure E2: Ambient noise and system validation measurement setup**

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/REN71UW</b>		Page <b>4(5)</b>
	Author Data <b>Andrew Becker</b>	Dates of Test <b>Mar. 09-10, May 27, July 12, 2011</b>	Report No <b>RTS-3640-1103-10B</b>



**Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup**

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW/REN71UW</b>		Page <b>5(5)</b>
Author Data <b>Andrew Becker</b>	Dates of Test <b>Mar. 09-10, May 27, July 12, 2011</b>	Report No <b>RTS-3640-1103-10B</b>	FCC ID <b>L6ARDM70UW L6AREN70UW</b>