Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic		Page 1(4)	
Author Data	Dates of Test	Report No	FCC ID	
Andrew Becker	March 1-23, 2012	RTS-5994-1204-08	L6ARFD30CW	


Annex E: Test set up photos

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic		Page <b>2(4)</b>	
Author Data	Dates of Test	Report No	FCC ID	
Andrew Becker	March 1-23, 2012	RTS-5994-1204-08	L6ARFD30CW	



Figure E1. BlackBerry Smartphone

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic		Page 3(4)	
Author Data	Dates of Test	Report No	FCC ID	
Andrew Becker	March 1-23, 2012	RTS-5994-1204-08	L6ARFD30CW	






Figure E2: Ambient noise and system validation measurement setup

Testing Services™
----------------------

Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFD31CW

4(4)

Author Data
Andrew Becker

Dates of Test
March 1-23, 2012

Report No RTS-5994-1204-08

FCC ID L6ARFD30CW






Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup