
	Document		Page
	<b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFL111LW</b>		<b>1(4)</b>
Author Data	Dates of Test	Report No	FCC ID
<b>Daoud Attayi</b>	<b>Dec. 19, 2012, Jan. 25, 2013</b>	<b>RTS-6026-1302-04</b>	<b>L6ARFL110LW</b>

## Annex E: Test set up photos


	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFL111LW</b>		Page <b>2(4)</b>
	Author Data <b>Daoud Attayi</b>	Dates of Test <b>Dec. 19, 2012, Jan. 25, 2013</b>	Report No <b>RTS-6026-1302-04</b>


Telecoil (-4, -8 mm)

Audio Output (0, 0)




Figure E1. BlackBerry Smartphone





**Figure E2: Ambient noise and system validation measurement setup**



**Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup**