
	Document		Page
	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFL111LW, RFP121LW		1(4)
Author Data Daoud Attayi	Dates of Test Dec. 19, 2012, Jan. 25, Feb. 13, 2013	Report No RTS-6026-1302-08	FCC ID L6ARFL110LW L6ARFP120LW

Annex E: Test set up photos


	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFL111LW, RFP121LW		Page 2(4)
	Author Data Daoud Attayi	Dates of Test Dec. 19, 2012, Jan. 25, Feb. 13, 2013	Report No RTS-6026-1302-08


Telecoil (-4, -8 mm)

Audio Output (0, 0)



Figure E1. BlackBerry Smartphone



	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFL111LW, RFP121LW		Page 3(4)
	Author Data Daoud Attayi	Dates of Test Dec. 19, 2012, Jan. 25, Feb. 13, 2013	Report No RTS-6026-1302-08





Figure E2: Ambient noise and system validation measurement setup




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup