
	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFV121LW		Page 1(4)
	Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1310-33

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFV121LW		Page 2(4)
	Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1310-33

Telecoil (5, 18 mm)

Audio Output (0, 0)






Figure E1. BlackBerry Smartphone



	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFV121LW		Page 3(4)
	Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1310-33






Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFV121LW		Page 4(4)
	Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1310-33




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup