
	Document		Page
	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFX101LW		1(4)
Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	June 12-13, 2013	RTS-6046-1307-27	L6ARFX101LW

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFX101LW		Page 2(4)
	Author Data Daoud Attayi	Dates of Test June 12-13, 2013	Report No RTS-6046-1307-27

Telecoil (5, 18 mm)

Audio Output (0, 0)





Figure E1. BlackBerry Smartphone








Figure E2: Ambient noise and system validation measurement setup

	Document		Page
	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFX101LW		4(4)
Author Data Daoud Attayi	Dates of Test June 12-13, 2013	Report No RTS-6046-1307-27	FCC ID L6ARFX101LW




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup