Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFY111LW			Page 1(4)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	May 31-June 06, 2013	RTS-6046-1308-25	L6ARFY11	0LW

Annex E: Test set up photos


Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFY111LW		Page 2(4)	
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attavi	May 31-June 06, 2013	RTS-6046-1308-25	L6ARFY11	0LW



Figure E1. BlackBerry Smartphone



Testing Services		Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model		
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	May 31-June 06, 2013	RTS-6046-1308-25	L6ARFY11	0LW






Figure E2: Ambient noise and system validation measurement setup

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic			Page <b>4(4)</b>
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	May 31-June 06, 2013	RTS-6046-1308-25	L6ARFY11	0LW



Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup