


| | | | |
|---|--|--------------------------------------|------------------------------|
|  | Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2) | | Page 1(4) |
| Author Data Daoud Attayi | Dates of Test Feb. 02-17, 2015 | Report No RTS-6063-1503-10 | FCC ID L6ARHC160LW |

Annex E: Test set up photos



| | | | |
|---|--|--|--------------------------------------|
|  | Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2) | | Page 2(4) |
| | Author Data Daoud Attayi | Dates of Test Feb. 02-17, 2015 | Report No RTS-6063-1503-10 |



Figure E1. BlackBerry Smartphone

| | | | |
|---|--|--|--------------------------------------|
|  | Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2) | | Page 3(4) |
| | Author Data Daoud Attayi | Dates of Test Feb. 02-17, 2015 | Report No RTS-6063-1503-10 |






Figure E2: Ambient noise and system validation measurement setup

| | | |
|--|--|--------------------------------------|
|  | Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2) | Page 4(4) |
| Author Data Daoud Attayi | Dates of Test Feb. 02-17, 2015 | Report No RTS-6063-1503-10 |
| FCC ID L6ARHC160LW | | |




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup