

深圳泰豐電子(香港)有限公司
SHENZHEN TAI FENG ELECTRONICS (HK) CO. LTD.

香港北角英皇道 510 號港運大廈 2205 室
UNIT 2205, ISLAND PLACE TOWER, 510 KING'S ROAD, NORTH POINT, HONG KONG.

電話號碼 : (852) 2111-1188 圖文傳真 : (852) 2111-9298
TELEPHONE NO.: (852) 2111-1188 FACSIMILE NO.: (852) 2111-9298

To :	Intertek Testing Services HK Ltd.	Fax :	2741-1693
Attn. :	Tommy Leung	Tel. :	2746-8219
c.c. :		Ref. :	SFENG990535
From :	Ricky Ng	Date :	Jan. 21, 2000
c.c. :		Page :	1 of 1

Subj.: Component Change of the Modified FF915

Please be informed that the new version FF915 has only the following change :

1. No change in PCB layout and circuit of the RF module of both handset and base.
2. There are new PCB layout and circuit design in the main boards of both handset and base.
3. The reason for the change is to reduce the BOM cost of the phone.

Please let me know if you have any queries.

Thanks & Best Regards,

Ricky Ng

ETL SEMKO ③			
Incoming Date:		21-1-00	
		By	
		Tommy Leung	