



Intertek Testing Services

November 18, 1999

Federal Communications Commission
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Mr. Joe Dichoso

Reference: Continental Conair Limited (Telson) FCC Part 95 Application
FCC ID: LBBFRS200
Confirmation # EA94589, Reference # 8858

Dear Mr. Dichoso:

This is in response to your email of 11/18/99 regarding FCC ID: LBBFRS200.

As I have mentioned to you, this is the same issue as the other application (FCC ID: OBAUBZAL14), they misclassify their unit and this application should be treated as original filing. Mr. Don Heo, the new manager recognizes the error and wanted to correct it with your help.

In behalf of our client therefore, we request that this multiple listing application be changed to original application and to give us additional time up to 11/27/99 to complete everything. New test report, photos, and documents will then be sent to you. The FCC identifier, FCC ID: LBBFRS200 will still remain the same

Thank you very much for your consideration regarding this matter.

Regards,

A handwritten signature in black ink, appearing to read "Gaspara Lim".

Gaspara Lim
Technical Writer

Intertek Testing Services NA Inc.

1365 Adams Court, Menlo Park, CA 94025
Telephone 650-463-2900 Fax 650-463-2910 Home Page www.worldlab.com