



June 19, 2013

Subject: Details of Change for IC: 6050B-860805/FCC ID: LCB-860805

To Whom It May Concern,

Please be informed that the equipment (Model: 01-860805-01) with IC: 6050B-860805 and FCC ID: LCB-860805 has been updated with a new firmware version 2.0. The new firmware adds a new modulation mode on the product with the following specifications.

Modulation Mode: 4LFSK

Channel Spacing: 12.5 KHz @ 9600 bps data rate
25.0Khz @ 19200 bps data rate

The above change details are presented to facilitate a Class 2 permissive change and re-assessment of the current certification of the product.

Sincerely,

A handwritten signature in black ink, appearing to read 'F. Riodique', with a long horizontal line extending to the right.

Ferdinand Riodique
Compliance Engineer
Topcon Positioning Systems, Inc.
7400 National Drive, CA 94550