


Label location





Model/Modèle: CW9164I-MR
Catalyst Wireless 9164I Wi-Fi 6E Series Access Point

Cisco Systems, Inc. (製造商/製造商)
170 West Tasman Drive, San Jose,
CA 95134 USA

Model (Modèle, 型号/型号): CW9164I-MR
Power (Alimentation, 输入/输入): 42.5 – 57 V = 776 – 579 mA
Product Name (產品名稱/產品名稱): 無線接入器/无线接入器
Made in Taiwan • Fabriqué à Taïwan • Hecho en Taiwán •
Изготовлено в Тайване (Китай) • 台灣製造/台灣製造
FCC ID: LDK-9160S2578 IC: 2461N-9160S2578 P/N: 74-127833-01
Indoor use only.




BARCODE
MFG Date: MM/YYYY



Model/Modèle: CW9166I-MR
Catalyst Wireless 9166I Wi-Fi 6E Series Access Point

Cisco Systems, Inc. (製造商/製造商)
170 West Tasman Drive, San Jose,
CA 95134 USA

Model (Modèle, 型号/型号): CW9166I-MR
Power (Alimentation, 输入/输入): 42.5 – 57 V = 847 – 632 mA
Product Name (產品名稱/產品名稱): 無線接入器/无线接入器
Made in Taiwan • Fabriqué à Taïwan • Hecho en Taiwán •
Изготовлено в Тайване (Китай) • 台灣製造/台灣製造
FCC ID: LDK-9160S2578 IC: 2461N-9160S2578 P/N: 74-127832-01
Indoor use only.



BARCODE
MFG Date: MM/YYYY





Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134 USA

Model/Modèle: CW9164I-B

Catalyst Wireless 9164I Wi-Fi 6E Series Access Point

Input: 42.5–57 V === 0.776-0.579 A

This device complies with Part 15 of the FCC Rules.
Operation is subject to the following two conditions:
1) this device may not cause harmful interference and
2) this device must accept any interference received,
including interference that may cause undesired operation.

FCC ID: LDK-9160S2578
Indoor Use Only



<http://cisco-returns.com>
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134
USA

SEE MANUAL BEFORE USE

MADE IN CHINA

56-107201-01



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134 USA

Model/Modèle: CW9166I-B

Catalyst Wireless 9166I Wi-Fi 6E Series Access Point

Input: 42.5–57 V === 0.776-0.579 A

This device complies with Part 15 of the FCC Rules.
Operation is subject to the following two conditions:
1) this device may not cause harmful interference and
2) this device must accept any interference received,
including interference that may cause undesired operation.

FCC ID: LDK-9160S2578
Indoor Use Only



<http://cisco-returns.com>
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134
USA

SEE MANUAL BEFORE USE

MADE IN CHINA

56-107201-01