

Cisco Systems, Inc. 320 Springside Drive Akron, Ohio 44333 Phone: 330 664-7900 Fax: 330-664-7922

http://www.cisco.com

May 30, 2002

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

RE: FCC ID: LDK102045 Attestation Statement

To Whom It May Concern:

Pursuant to Part 15.407(c) of the FCC rules addressing Unlicensed National Information Infrastructure radios, the Cisco Systems U-NII radio, FCC ID: 102044, will, via MAC layer software, automatically discontinue transmission in case of absence of information to transmit. The radio will also automatically discontinue transmission upon operational failure of the device via transmitter hardware control in instances of hardware or MAC layer software failures.

Best Regards,

Jim Nicholson

EMC Compliance Engineer

Phone: (330) 664-7362 Fax: (330) 664-7301 E-Mail: jimnicho@cisco.com