

August 28, 2013

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Cisco Systems will establish a new FCC ID: LDK102087P under Cisco Systems grantee code for purpose of marketing. The original grant to Cisco Systems will remain in effect.

## Per 2.933(b)

- 1. The original identification is LDK102087
- 2. The original grant date is 08/15/2013
- 3. The equipment is electrically identical. Only the model name and FCC ID number are different.
- 4. The original test results are applicable and representative of this changed device.
- 5. The purpose of the change of ID is to add anew model that will be marketed for indoor and outdoor use with progressional installation. A C2PC will be filed once that change in ID has been granted to modify that grant conditions to limit this new version to professional installation
- 6. Exterior photographs are included in this application.

The following files are electronically submitted as attachments: Cover Letter

**External Photos** 

FCC ID label format and location

**Best Regards** 

Jim Nicholson Compliance Engineer

Cisco Systems, Inc.