


## Label and location



Label location  
Back of the device



Control



LAN



HDMI Input



USB C



HDMI Output



USB A



Service



Microphone



Microphone




Audio Line Out



Factory Reset



Power Input



IS 13252 (Part 1)/ IEC 60950-1

IFT: XXXXXXyy-yyyy

FCC ID : LDK603102338

CMIIT-ID: yyyyXXyyyy

IC : 2461N-603102338

CAN ICES-3(A)/NMB-3(A)

5.2/5.3GHz is limited to indoor use only in Japan



R-XXXXXXXXX  
www.bis.gov.in

CONTAINS APPROVED RADIO MODULE CERTIFIED NUMBER: 201-190982 and R-C-TNY-P3310



**TELEPERMIT**  
Telepermit holder:  
Cisco Systems (NZ) Ltd  
Product:  
Cisco Webex Board Model  
TTC60-31 and TTC60-32  
PTC 216 / 21 / 004

RAMATEL X-00000

Complies with  
IMDA standards  
DB101992



本產品內含視頻模組  
CCAF18LP1980T3

XU101307-18046 모니터  
R-R-TNY- XXXyy-yy  
전화: +82-2-3429-8000

**ANATEL**  
00658-19-01086

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134, USA

Designed by Cisco(思科研发 / Conçu par Cisco)

www.cisco.com

Product name (产品名称 / 器材名稱/Nom Du Produit): Cisco Webex Board Pro 55 视频会议终端

Model (型号 / 型號 / Modèle):TTC60-31

Contains FCC ID: LDKNVTX21737 Contains IC: 2461N-NVTX21737



Made in China 中国制造

Fabriqué en Chine

Mfg. site:

Mfg. date / Date de fabrication: DDMMMYYYY

This device complies with Part 15 of the FCC Rules.

Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

Apparatet må tilkoples jordet stikkontakt. Apparaten skall anslutas till jordat uttag. Laite on liitettävä suojakoskettimilla varustettuun pistorasiaan. Apparatets stikprop skal tilsluttes en stikkontakt med jord, som giver forbindelse til stikproppens jord.

P/N:



S/N:



COO:



MAC:



PID/VID:



Warning: Shock hazard - Do not open  
AVIS: Risque de choc électrique - Ne pas ouvrir  
警告: 电击危险-不要打开

Power input (輸入/Entrée):100-240VAC, 3.5-2.5 A, 50/60 Hz