

Cisco Systems, Inc.

170 West Tasman Dr., San Jose, CA 95134 USA

Declaration of changes from Initial VC9253 & VC9240 to Variant CP-840S & CP-840

General: \_\_\_\_ is a variant product of \_\_\_\_.

● SOFTWARE MODIFICATIONS:

- Protocol Stack changes: No
- MMS/STK/USAT/USIM changes: No
- DM/SUPL/VT/FUMO/SWP/HCI: No

Other changes detailed:  
The SW image icon will be different.

● HARDWARE MODIFICATIONS:

- Baseband changes: NO
- Band changes: NO
- Antenna changes: NO
- PCB Layout changes: NO
- Main components changes: NO


	Antanna	AP	MODEM	Transceiver	Balun	Band pass filter	diplexer
Bluetooth	NO	NO	NO	NO	NO	NO	NO
wifi	NO	NO	NO	NO	NO	NO	NO

- Bluetooth changes: NO
- WiFi changes: NO
- FM changes: NO
- NFC changes: NO
- Other components changes: NO
- TP/LCD/ Camera changes: NO
- Other changes detailed: NO

● MECHANICAL MODIFICATIONS:

- Use new metal front/back cover or keypad: No change
- Mechanical shell changes:
  - Whole size of EUT: No
  - Distance of Ear reference point to bottom of handset: No change
  - Other trinkets to change the surface of handset: the TP & back cover & battery label, logo change from Spectralink to Cisco
- Other changes detailed:
  - The materials do not change.

APPROVED BY:

Project Manager:  
 Signature:   
 Date: 20. 11. 15