



**Model / Modèle: CP-860S**  
 (P) P/N: 74-125898-01 Rev 01 C  
 IC: 2461N-8602237 CAN ICES-3(B)/NMB-3(B)  
 FCC ID: LDK8602237  
 Made in China / Fabriqué en Chine  
 Manufacturer / Fabricant: Cisco Systems, Inc.

SN: TCL12345678  
 Vent Port Do Not Puncture /  
 Orifice de ventilation Ne pas percer

MAC: 1234567890AB  
 Board SN: VELC1234567890A  
 Cisco Systems, Inc. 170 W. Tasman Dr.,  
 San Jose, CA 95134, U.S.A.

[www.cisco.com](http://www.cisco.com)

Reset / Réinitialiser  
 IP68  
 BC  
 R-NZ E503

IC CE FC E 134

Label



Label Location