




Cisco Systems, Inc.  
 170 West Tasman Drive  
 San Jose, CA 95134-1706  
 Phone 408 526-4000  
 Fax: 408 526 -4100  
<http://www.cisco.com>

### Label Location Diagram CP-8831



**Model:** Cisco UC Phone CP-8831  
**型号/Modèle:** Cisco UC 电话 CP-8831  
**Manufacturer(制造商/Fabricant):** Cisco Systems, Inc.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

声明: 此为A级UC系统产品附件(中国大陆), 在生活环境中, 该产品可能会造成无线电干扰. 在这种情况下, 可能需要用户对其干扰采取切实可行的措施.

警告使用者: 這是甲類的資訊產品, 在居住的環境中使用時, 可能會造成射頻干擾. 在這種情況下, 使用者會被要求採取某些適當的對策.

**Input(輸入):** 48V 0.38A

**D120245003**  
**003-120332**  
**FCC ID:** LDK88310768  
**CANADA IC:** 2461B-88310768  
  
<http://cisco-europe.com>

**TAN:** 74=11133=01 A0+  
  
**PID VID:** CP-8831-BASE-S= V01

**SN:** FCH16512AVY  
  
**MAC:** 001F9EABF5DB  
  
**Made in China 中国制造**  
[www.cisco.com](http://www.cisco.com)

↑  
 BARCODE DISPLAYED HERE ARE DEMO PURPOSES ONLY.