



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526 -4100
<http://www.cisco.com>

May 19, 2016

FCC ID: LDK88611057 CP-8861

Submit a permissive Change to FCC Grant FCC ID: LDK88611057

This Device was previously authorized under 15.247 to be modified to operate under the New Rules and technical requirements of 15.407 (b) (4) (i) with no changes in total power. This Device will be sold after 2020.