




Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526-4100
<http://www.cisco.com>

Exhibit : Internal Photos


Model: Cisco CGR 1240
FCC ID: LDKALTMT0556
IC ID: 2461B-ALTMT0556

CGR-1240 : Internal PCB Mother Board (Bottom)



EDCS-1118876

CGR-1240 : Internal PCB Mother Board (Top)






Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526-4100
<http://www.cisco.com>

Exhibit : Internal Photos


Model: CGR1240
FCC ID: LDKALTMT0556
IC ID: 2461B-ALTMT0556

CGR1240 : Internal PCB Mother Board (Bottom)




EDCS-1118876


CGR1240 : Internal PCB Mother Board (Top)



CGR1240 : Internal PCB Daughter card (Top)




CGR1240 : Internal PCB Daughter card (Bottom)



CGR1240 : 2400MHz DTS transmitter section close up



CGR1240 : 2400MHz DTS transmitter connector and Antenna



2400MHz DTS Tx connector & Antenna assembly