



Cisco Systems, Inc
170 West Tasman Drive
San Jose, CA 95134

May 26, 2015,

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Cisco Systems will establish a new FCC ID: LDKIW3702 under Cisco Systems grantee code for purpose of marketing. The original grant to Cisco will remain in effect.

Per 2.933(b)

1. The original identification is LDK102087P
2. The original grant dates are
 - a. DTS: 06/05/2014
 - b. U-NII: 07/11/2014
3. The equipment is electrically identical. Only the model name and FCC ID number are different.
4. The original test results are applicable and representative of this changed device
5. The purpose of the change of ID is to add a new model that will be marketed for industrial and hazardous locations. A C2PC will be filed once this change of ID has been granted to modify this grant to include the physical modifications.
6. External photos, labels, and this cover letter are included in this application.
7. Additional attestation documents will be provided as needed.

The following files are electronically submitted as attachments:

- a. This Cover Letter
- b. External Photos
- c. FCC ID label format and location
- d. Configuration Guide
- e. Software Security Checklist
- f. Attestations for SDR compliance and DFS compliance

Note: The original FCC ID and grant and the new FCC ID and grant belong to the same grantee, Cisco Systems and the grantee retains full responsibility for security and configuration control for both FCC IDs and grants.

If you have any questions regarding this application, please feel free to contact me.

Best Regards

A handwritten signature in blue ink that reads 'Steve Granzella'.

Steve Granzella
Compliance Engineering Manager
Cisco Systems, Inc