



Antenna Compliance with FCC 15.203


There are two antennas on the Model 24965 Patient Connector.

Both antennas, the Bluetooth and the inductive telemetry, are soldered to the PCB, and as such are considered permanently attached.

Bluetooth Antenna Information

Manufacturer	Model Number	Gain (dBi)	Description
Murata	LDA212G3110K	+0.9	Chip antenna

Bluetooth Antenna Physical Dimensions



Inductive Telemetry Antenna Information

Manufacturer	Model Number	Description
Precision Incorporated	019-7353-01R 101916	Split coil loop antenna