FCC TEST REPORT Report No.: F373016

1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

Issued : Aug, 21, 2003

Page No.: 1 of 3

: LFUSR181B

FCC ID

FCC TEST REPORT Report No.: F373016



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : LFUSR181B

 TEL: 886-2-2696-2468
 Page No. : 2 of 3

 FCC TEST REPORT Report No.: F373016

1.2. Photographs of Radiated Emission Test Configuration

The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : LFUSR181B Page No.: 3 of 3

Issued : Aug, 21, 2003